

Ecoprotect: Case study Dendermonde, Belgium



1. Date: 28/08/2012
Preparation of the slope



2. Date: 29/08/2012
Sowing of grasses



3. Date: 29/08/2012
Installation of Ecoprotect



4. Date: 5/09/2012
Grasses start to develop



5. Date: 5/09/2012
Grasses start to develop



6. Date: 31/10/2012
Successful greening of the slope!